

**DWM Incomplete Work Areas
in
Brookhaven Rights-of-Way**

73 Total Locations Requiring DWM Repairs (DWM Work Orders)				11 Known DWM Work Orders Completed, 8/21-Present			8 Locations with Road Plates Covering Needed Repair	
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	AREA AND TYPE	Road Plate Used	COMMENTS	
2059434		8/7/2020	1462 Brawley Circle	Brawley Circle	Two depressions in the road 3-inches deep formed last year and no repairs have been made. First Reported on 8/7/2020.			
2063959		8/19/2020	4180 Berkford Circle	Berkford Circle	A depresion in the road 3-inches deep formed last year and no repairs have been made. First reported on 8/29/2020.			
21018225		2/25/2021	1157 Victoria St NE	Victoria St NE	A cave in on the shoulder extending to a previous DWM repair of a water main in the roadway. The cave in has caused the curb & gutter to sink and the old repair as well. DWM filled the cave in with dirt and it has dropped once more. No other repairs were made to the road and curb & gutter.			
21031968		4/14/2021	3249 Lynwood Dr NE	Lynwood Dr NE	A sinkhole has formed over the water main and lateral service line to this property.			
21045221	12/22/2021	5/18/2021	2967 Surrey Ln NE	Surrey Ln NE	A large and deep sinkhole has formed under the roadway above the water main and the SS lateral connection to this property. The sinkhole is 7-ft deep and runs from the middle of the road to the mailbox. DWM Has concluded their water and SS service lines to be in good shape. The City of Brookhaven PW Dept. will repair the sinkhole.		The sinkhole will be repaired by the PW Dept. with WO 7937	
21079815		5/21/2021	2791 Ashford Rd	Ashford Rd	Sinkhole has formed over the SS sewer line and service line to this property. 3 road plates have been installed in front of this property and another at 2788 Ashford Rd			
21042739		5/21/2021	2888 N Thompson Rd NE	N Thompson Rd NE	<u>Road plates</u> and barrels intalled on sinkhole occurring over SS line in the middle of the road for more than a year	X	Two of the three trenches have been repaired and the pavement repaired. There is no evidence that a concrete cap was installed.	
21048724		5/24/2021	1855 Tobey Rd NE	Tobey Rd NE	A sinkhole formed 6-ft deep, 6-ft in length and, 4 -feet wide underneath the road in line with the sanitary sewer line from this property to the middle of the road. No one has come to investigate and to repair it.			
21071897		5/27/2021	3108 Mabry Rd NE	Mabry Rd NE	A very large depression has occureed above the SS line in the middle of the road.			
21051716		6/7/2021	1197 Dorby Park NE	Dorby Park NE	Repairs were made for a water leak more than a year ago with WO 2041382. The driveway and the shoulder were repaired by the City of Brookhaven with an agreement with Dekalb County. The road was not included and has yet to be repaired.			
21051781		6/21/2021	1382 Etowah Dr NE	Etowah Dr NE	Initial repairs by DWM left a mess on the shoulder of the road and a sinkhole formed underneath the curb and gutter and on the middle of the intersection with Ellijay Dr.			

**DWM Incomplete Work Areas
in
Brookhaven Rights-of-Way**

73 Total Locations Requiring DWM Repairs (DWM Work Orders)			11 Known DWM Work Orders Completed, 8/21-Present			8 Locations with Road Plates Covering Needed Repair	
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	AREA AND TYPE	Road Plate Used	COMMENTS
21056675 21059890	10/21/2021	6/28/2021	2636 Apple Valley Rd NE	Apple Valley Rd NE	Initially repaired with WO 21056675. Another sinkhole open up next to it.		The road has been repaired.
Emergency		6/28/2021	2791 Ashford Rd NE	Ashford Rd NE	DWM responded to an emergency for the sanitary sewer lateral lines at 2794, 2791 and a third location. A pump system has been installed to bypass these locations and one lane has been closed. The road will be closed during the repairs of the SS laterals. Dekalb Safety Office Julian A Reasonover was notified of the lack of traffic control devices for the lane and road closure.	X	
21057295		7/6/2021	1321 N Cliff Valley Way	N Cliff Valley Way	A deep depression was noted next to a DWM manhole in the curb and gutter. No work has been done.		
2038829	11/18/2021	7/9/2021	2464 Oostanaula Dr NE	Oostanaula Dr NE	A cut on the road was made for repairs to SS lateral. GAB was added instead of a street road plate.		The road was repaired and the WO closed.
21062135		7/12/2021	2622 Briarcliff Rd NE	Briarcliff Rd NE	Potholes repaired by PW. Water spewing from the edge of the repair potholes may indicate an issue with the water service lateral. The original issue has been repaired and the pavement repaired. Two other trenches were made across the street. One is filled with GAB and the other is covered with a road plate.	X	Information updated on 1/21/2022
21062135		7/12/2021 1/18/2022	2622 Briarcliff Rd NE	Briarcliff Rd NE	Pothole has opened up once more due to constant water spewing from it. First reported on 7/12/21. The City of Brookhaven Street crew repaired only the pothole due to the delay by DWM responding to our SR. A second SR has been submitted on 10/6/21. DWM has excavated the pothole and installed a road plate.	X	The water leak has been repaired and a poorly installed asphalt patch is in its place. Two other trenches have been made across the street. One has GAB and the other is covered with a road plate.
21063205		7/15/2021	1897 E Roxboro Rd NE	E Roxboro Rd NE	Work on fire hydrant. Tree on the sidewalk and sinkhole at edge of it. DWM cones installed. There is a small sinkhole next to the fire hydrant.		The tree has been removed but the ground around the fire hydrant has yet to be repaired.
		7/16/2021	4081 Ashford Dunwoody Rd	Ashford Dunwoody Rd	Dekalb Watershed removed 3 sections of sidewalk for emergency repairs to the watermain. The sidewalk has not yet been repaired.		
21059863 21061956		7/16/2021	2183 Drew Valley Rd	Drew Valley Rd	There was a large water main break recently and the granite curb was removed and the shoulder of the road in two locations was disturbed for the repairs. Mud was left on the road and the shoulder was not graded properly.		
2106357		7/16/2021	3213 Osborne Rd NE	Osborne Rd NE	A pothole has formed over the water main in the middle of the road.		
21063658		7/16/2021	1874 Tobey Rd NE	Tobey Rd NE	A large depression 3-inches deep has formed over the SS in the middle of the road.		
21067792 21105540		11/16/2021	3027 Templewood Dr	Templewood Dr	A sinkhole had formed in the middle of the road above the sanitary sewer main. The sinkhole in the middle of the street was repaired. The depression and sinkhole underneath the granite curb has yet to be completed		WO 21067792 was noted as completed on 11/16/2021
21069929		8/3/2021	1514 Ragley Hall Rd NE	Ragley Hall Rd NE	A depression formed underneath the sidewalk. The sidewalk collapsed 3-inches above the sanitary and water service lines to this property.		
21070481		8/4/2021	2522 Skyland Dr NE	Skyland Dr NE	A sinkhole formed over the water service line to this property at the edge of the road underneath the granite curb		

**DWM Incomplete Work Areas
in
Brookhaven Rights-of-Way**

73 Total Locations Requiring DWM Repairs (DWM Work Orders)				11 Known DWM Work Orders Completed, 8/21-Present		8 Locations with Road Plates Covering Needed Repair	
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	AREA AND TYPE	Road Plate Used	COMMENTS
21071905		8/9/2021	2132 Havenwood Trail NE	Havenwood Trail NE	The water meter on the sidewalk has sunk and created a dangerous trip hazard.		
21071907		8/9/2021	3382 Stratfield Dr. NE	Stratfield Dr. NE	Sidewalk collapsing due a possible failure of the service line from the water meter.		
21072936		8/12/2021	1266 Fairhill Ln	Fairhill Ln	A depression formed underneath the SS service line from the road to the edge of the ROW		
21069526 21069527 21069528		8/12/2021	1358 Old Johnson Ferry Rd	Old Johnson Ferry Rd	A water main leak occurred underneath the sidewalk. DWM removed the sidewalk and granite curbs and damaged the rest of the sidewalk to the ADA ramp. The street sign was taken down and debris was left in the road and on the property front yard. Only two cones were installed and the area was not properly secured.		
		8/16/2021	2141 Drew Valley Rd	Drew Valley Rd	Repairs to a water main leak were completed. DWM left a mess on the shoulder of the road. There is a large depression on the location of the repairs and mud on Drew Valley and Burch Circle.		DWM did not provided a WO #
21063615		8/31/2021	1377 Dresden Dr NE	Dresden Dr NE	A water leak was reported near the sprinkler system on the back of the curb. DWM has investigated and placed safety cones and two road plates. The road plate near Fernwood Circle was not secured and had to be repositioned by OPTECH. A request has been made to DWM to properly secure the road plate.	X	
21083449		9/8/2021	1082 Mendel Circle	Mendel Circle	Sinkhole has formed over the SS sewer line and service line in the middle of the road.	X	City placed plate over DWM sinkhole.
21028191	9/23/2021	9/8/2021	1486 Ragley Hall Rd NE	Ragley Hall Rd NE	The sidewalk was removed for repairs to the water service line to this property		The sidewalk and landscaping have been repaired.
21081563		9/8/2021	1485 Stratfield Circle	Stratfield Circle	Dekalb Watershed removed 2 sections of sidewalk for the replacement of water main service line.		
1961627	1/22/2022	9/8/2021	1078 Wimberly Rd	Wimberly Rd	The road is caving in above the sanitary sewer line and the service lines to the residents of the street. DWM conducted a CCTV inspection and reported no problems with the mainline. No information was given regarding the service lines. The problem is the poor compaction of the GAB and the contractor for DWM not installing a concrete cap as it is required under theirs and our construction standards.		Contact Mr. Hollingsworth DWM inspector at 678-614-5283 for CCTV report of the SS Line. The PW Dept has installed a temporary asphalt patch on all the major depressions in the middle of the road with WO 7977
21085424		9/14/2021	4560 E Brookhaven Dr	E Brookhaven Dr	Large depression has formed in the middle of the road near the sanitary sewer line.		
21091053		9/28/2021	2332 Drew Valley Rd	Drew Valley Rd	There is a large depression over the sanitary sewer service line in the middle of the road.		
21091041	12/8/2021	9/28/2021	1575 Grant Dr	Grant Dr	Sanitary Sewer manhole concrete collar broken and a small sinkhole next to it.		The concrete collar and small sinkhole have been repaired.

**DWM Incomplete Work Areas
in
Brookhaven Rights-of-Way**

73 Total Locations Requiring DWM Repairs (DWM Work Orders)			11 Known DWM Work Orders Completed, 8/21-Present			8 Locations with Road Plates Covering Needed Repair	
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	AREA AND TYPE	Road Plate Used	COMMENTS
21074326		9/29/2021	2546 Drew Valley Rd	Drew Valley Rd	A water main break was reported and DWM repaired the line. The sidewalk was removed and mud left in the roadway. The sidewalk has not yet been repaired.		Resident called 11/15/21 to report this again. They also may have replaced one S/W panel and left one a few feet away open. Sod, backfill, and stabilization of repair pit necessary too.
2080425		9/29/2021	1232 W Nancy Creek Rd	W Nancy Creek Rd	Sidewalk removed for a water service line repairs		
21091564 22001249		10/1/2021 01/13/2022	2484 Oostanaula Dr. NE	Oostanaula Dr. NE	Three road plates installed over a trench for a water main break repaired on 7/22. 3 road plates have been installed and there is a water leak near the fire hydrant spewing water to the road.	X	
21092165		10/1/2021	3013 Surrey Ln	Surrey Ln	The road is collapsing from the driveway to the center of the road to the sanitary sewer line. DWM has been notified.		
21088146		10/4/2021	3389 Woodrow Way	Woodrow Way	Recent repairs to the sanitary sewer or water service lanes were completed but the ground was not properly graded and not fully restored.		Sod to be replaced. No schedule date has been provided by DWM.
21093922		10/7/2021	2577 Ashford Rd	Ashford Rd	The shoulder of the road has been disturbed for the repairs to a water service line to this property. It needs to be regraded. Two potholes to exposed water valves were made at the intersection of Dresden Dr. and Ashford Rd.		
21094283		10/12/2021	3882 Ashford Dunwoody Rd	Ashford Dunwoody Rd	DWM made repairs to a water main break and damaged the sidewalk at both ends and behind of it. The water break caused the sidewalk to sink before the catch basin creating a trip hazard. DWM has to demo and repair the sidewalk. The repairs were made the first week of October.		
		10/25/2021 1/18/2022	1310 Ragley Hall Rd	Ragley Hall Rd	A failure of the water service line to this home was reported and repaired by DWM. Approximately 15-ft of the sidewalk was removed and the entire work is closed with safety cones and caution tape. DWM did not clean the road and left mud all over. The site has yet to be repaired and the broken sections of the sidewalk not removed. A request was made for DWM to return and cleanup the site as well as to safegurd it properly.		
21100570		10/25/2021	1095 Victoria St	Victoria St	The gutter in front of this home has sunk and appears to be related to the water service line or sanitary service line to this property.		
		10/25/2021	1111 Victoria St	Victoria St	The road is caving in and the curb and gutter have broken above the water service line to this property.		
21100337		10/25/2021	1120 Victoria St	Victoria St	Repairs to a water service line to this home were completed by DWM and GAB added to the trench. No concrete cap was installed and the road has yet to be repaired.		
21102619		11/2/2021	1191 Oglethorpe Ave	Oglethorpe Ave	A large sinkhole was found during the FDR on the road. DWM was contacted for an emergency repairs and to install road plates. The pavement project is on hold until this is repaired.		DWM made repairs to the manhole and OPTECH covered the sinkhole. The sinkhole opened up one week later.
21101427		11/5/2021	4218 Oak Forest Dr.	Oak Forest Dr.	Recent repairs to the water main were completed at the intersection of Oak Forest with Ashwoody Trail. The pavement was repaired. Now water is leaking near one of the water valves in the newly installed landscaping of this property. Water is traveling from the water valave to the road.		

**DWM Incomplete Work Areas
in
Brookhaven Rights-of-Way**

73 Total Locations Requiring DWM Repairs (DWM Work Orders)			11 Known DWM Work Orders Completed, 8/21-Present			8 Locations with Road Plates Covering Needed Repair	
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	AREA AND TYPE	Road Plate Used	COMMENTS
		11/8/2021	1205 Club Walk Dr	Club Walk Dr	A cut to the road, curb and gutter and the driveway to this property was made for repairs to the water main. The trench was filled with GAB and safety cones installed. The road was not cleaned and a road plate was not installed as required.		DWM has not provided a WO #
21105540		11/16/2021	3027 Templewood Dr	Templewood Dr	A sinkhole has formed underneath the granite curbs near the water main and water service line in this property and the granite curbs have sunk.		
21049119	11/18/2021	11/8/2021	3517 Ashford Dunwoody RD NE	Ashford Dunwoody RD NE	Two trenches were repaired almost two years ago and DWM failed to installed a concrete cap on both of them. Both are sinking and have to be repaired asap.		The trenches have been repaired by the PW Dept.
21105980	12/7/2021	11/18/2021	3940 Clairmont Rd	Clairmont Rd	A sinkhole has formed on the northbound lane of Clairmont Rd before Airport Blvd. It appears to be a cavity formed during recent repairs to the water main above this location.		DWM has responded by denying it has to do with the recent repairs above this location. The City PW Dept. will repair the road with WO 2015
21109255		11/24/2021	1663 Dresden Dr.	Dresden Dr.	A large sinkhole has developed above the the SS line in the road. The depression is approximately 5-ft in length, 3-ft wide, and 6-inches deep. A request to install a road plate was made.		
21104195 21114229		12/7/2021	2599 Apple Valley Rd	Apple Valley Rd	Two large road plates were installed by DWM for repairs to the sanitary sewer line over 5 months ago. The first WO is for the street repairs and the second is for securing the road plates.	X	
		12/9/2021	1022 Citadel Dr.	Citadel Dr.	The sewer manhole ring has broken and the lid could potentially drop in the manhole.		
		12/10/2021	1490 Grant Ave	Grant Ave	Recent repairs to the water main were completed and mud was left in the driveway and the road in front of this property. The trench in the roadway was filled with GAB above the road surface and safety cones and caution tape were installed. A request was made to DWM to remove the GAB and to install a road plate and clean up the mud from the road.		No road plate or improvements to the area have been made by DWM as of 1/21/22
21115396		12/13/2021	3517 Ashford Dunwoody RD NE	Ashford Dunwoody RD NE	The trench near the second entrance to Blackburn park has begun to sink once more after completion of the repairs by the City PW Dept. DWM has been notified of our repairs and installation of a concrete cap.		
No WO given	9/17/2021	7/22/2021	1054 Beech Haven Rd NE	Beech Haven Rd NE	A cut in the road was made measuring 5-ft wide by 8-ft length and 6-inches deep and no road plate was installed. The cut in the road is at the exit of Beech Haven to Sheridan Rd and creates a condition for possible vehicular accidents. This was reported to the Safety Officer for Dekalb Julian A Reasonover		The road was repaired.
21012958			2002 Drew Valley Rd	Drew Valley Rd	There is a large depression over the sanitary sewer service line to this property.		
		8/31/2021 1/14/2022	3219 Georgia Ave	Georgia Ave	A cut in the road and the concrete C&G was made for repairs to the water main. 2 safety cones were installed without caution tape and GAB added to the trench. Repairs have not been completed and the trench is exposed		
21023844		12/15/2021	3246 Lynwood Dr	Lynwood Dr	A depression has form over the sanitary sewer line. It is approximately 3-inches deep and it is happening on an old road repairs. It seems to be the SS service line to this property.		

**DWM Incomplete Work Areas
in
Brookhaven Rights-of-Way**

73 Total Locations Requiring DWM Repairs (DWM Work Orders)			11 Known DWM Work Orders Completed, 8/21-Present			8 Locations with Road Plates Covering Needed Repair	
DWM WO	Observed Completion Date	Reported Date	ADDRESS	Street	AREA AND TYPE	Road Plate Used	COMMENTS
22000222		1/3/2022	1951 Dresden Dr	Dresden Dr	A depression on the concrete gutter has been reported to DWM. This is located above their SS line and on the transition lane to Clairmont Rd.		
		1/7/2022	1531 Dresden Dr	Dresden Dr	Pressure on the water main is causing to spew water to the road from the water valves located on the intersection of Dresden Dr. and Thompson Rd, on Dresden Dr. and Grant and, on Thompson Rd and Grant.		
22001276	1/12/2022	1/7/2022	3519 Sunderland Way	Sunderland Way	A possible failure has been reported on the water main T-connection on Johnson Ferry Rd with Sunderland Way. Every time a truck passes over the broken concrete the water service line to this property shakes and the whole house as well.		DWM determined the pothole was not located above the water main and thus not related to the shaking of the home nor for the breaking of the paving in the road.
22001232		1/11/2022	2638 Drew Valley Rd	Drew Valley Rd	Repairs to a water valve and water main were made and it damaged the ADA ramp. The water valve was left above the surface of the road.		
22001231		1/11/2022	2512 Drew Valley Rd	Drew Valley Rd	Repairs to the water main were made on the side facing Thompson Rd. The roadway was not cleaned and the shoulder was not restored. A request was made for the mud to be removed from the road and the shoulder restored in Kind.		
No WO given	1/13/2022	1/11/2022	1357 Brook Forest Dr	Brook Forest Dr	Repairs to the water main were made on the pavement and shoulder of the road. The granite curb was damaged and a 5-inch pothole has formed due to recent rainstorms washing the GAB from the trench. A request was made for the installation of a road plate, restoration of the shoulder and, installation of new granite curb.		The repairs to the road and the granite curb on both sides of the road will be repaired by the PW Dept. with WO 7969
22005805		1/19/2022	2467 Ellijay Dr	Ellijay Dr	A sinkhole has formed on an area where DWM has made repairs to the SS main. The sinkhole is expanding towards the manhole located in the middle of Ellijay Dr. but has yet to collapse. One at the intersection of Etowah and Ellijay has been closed and secured with barrels, cones and caution tape.		
21060247		1/19/2022	3407 Breton Ct	Breton Ct	DWM made repairs to the water service line to this property and to the water valve located in the gutter. DWM left the water valve almost 1-foot above the gutter and failed to repair the concrete curb and gutter.		
21042779 22005963		5/12/2021 1/20/2022	4034 Chippewa Pl	Chippewa Pl	A sinkhole formed in the middle of the road above the sanitary sewer on a previous repair patch by DWM. A request was made for a road plate to be install over it.		